Setup Photographs

<Conducted Emission>



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AET6-0610 Page Number : 1 of 4
Report Issued Date : Jan. 21, 2016
Report Version : Rev. 01

Report No.: FR552738-01A


<Radiated Emission>

X Plane for Ant. 2

LF



HF




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AET6-0610 Page Number : 2 of 4 Report Issued Date: Jan. 21, 2016 Report Version : Rev. 01

Report No.: FR552738-01A

Report No.: FR552738-01A

Z Plane for Ant. 1






TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AET6-0610 Page Number : 3 of 4
Report Issued Date : Jan. 21, 2016
Report Version : Rev. 01




Y Plane for Ant. 2 (EUT with Base)

LF



HF



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AET6-0610 Page Number : 4 of 4
Report Issued Date : Jan. 21, 2016
Report Version : Rev. 01

Report No.: FR552738-01A