


Report No.: FR5D3034-01D

# **Setup Photographs**

## <Conducted Emission>



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AETH-1210 Page Number : 1 of 2 Report Issued Date: Apr. 26, 2016 Report Version : Rev. 01


Report Template No.: BU5-FR15EWL Version 1.4



## <Radiated Emission>

### **Z** Plane

LF



### HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AETH-1210 Page Number : 2 of 2
Report Issued Date : Apr. 26, 2016
Report Version : Rev. 01

Report No.: FR5D3034-01D

Report Template No.: BU5-FR15EWL Version 1.4