
Setup Photographs


<Radiated Emission>

Y Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AETK-1013 Page Number : 1 of 2
Report Issued Date : Dec. 21, 2015
Report Version : Rev. 01


Report No.: FR5O0723-01A

Report Template No.: BU5-FR15CBT4.0 Version 1.1

Report No. : FR5O0723-01A

Y Plane with Plastic Loop

HF



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AETK-1013 Page Number : 2 of 2
Report Issued Date : Dec. 21, 2015
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0 Version 1.1