

Setup Photographs

<Conducted Emission>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AETL-0725 Page Number : 1 of 4
Report Issued Date : Jun. 08, 2016
Report Version : Rev. 01

Report No.: FR572808-01E





Rear View

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AETL-0725 Page Number : 2 of 4
Report Issued Date : Jun. 08, 2016
Report Version : Rev. 01




<Radiated Emission>

MIMO Mode

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AETL-0725 Page Number : 3 of 4
Report Issued Date : Jun. 08, 2016
Report Version : Rev. 01


Report No.: FR572808-01E




Report No.: FR572808-01E

SISO Mode

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AETL-0725 Page Number : 4 of 4
Report Issued Date : Jun. 08, 2016
Report Version : Rev. 01