Ring LLC

1523 26th Street, Santa Monica, California 90404, United States

Date: January 2, 2019

FCC ID: 2AEUPBHAMS001

Model Number: 5SM1S8

To:

Federal Communication Commission Authorization and Evaluation Division 7435 Oakland Mills Road Columbia, MD 21048

To Whom It May Concern,

We, *Ring LLC*. hereby declare that our product (**Motion Sensor**) Model Number: **5SM1S8** will disable Bluetooth Classics function (Bluetooth V5.0) and BT 2LE by software and only open BT LE (Bluetooth V5.0) although Bluetooth modular nRF52832 support both Bluetooth LE (Bluetooth V5.0, including BR LE and BT 2LE) and Bluetooth Classics (Bluetooth V5.0) due to marketing purposes. End-user will only use BT LE (Bluetooth V5.0) in USA market.

Should you have any questions or comments regarding this matter, please have my best attention.

Best Regards!

Sincerely,

(Signed)

Name / Title: Michael Recker / CTO, Ring Beams

Company: Ring LLC

Address: 1523 26th Street, Santa Monica, California 90404, United States

Phone: 8006561918 Fax: 3102272217

E-Mail: michael.recker@ring.com

wishel Rolm