



Appendix A. Test Photos 1. Photographs of Conducted Emissions Test Configuration



Report No.: FR5N2432AC

FRONT VIEW



REAR VIEW


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A1 of A6 : Rev. 02

Report Version



CC Test Report No. : FR5N2432AC



SIDE VIEW

SPORTON INTERNATIONAL INC. Page No. : A2 of A6
TEL: 886-3-327-3456 Report Version : Rev. 02

FAX: 886-3-327-0973



FCC Test Report Report No.: FR5N2432AC

2. Photographs of Radiated Emissions Test Configuration For radiated emissions 9kHz~30MHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A3 of A6 Report Version : Rev. 02




FCC Test Report Report No.: FR5N2432AC

For radiated emissions 30MHz~1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A4 of A6 : Rev. 02

Report Version




FCC Test Report No.: FR5N2432AC

For radiated emissions above 1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A5 of A6
TEL: 886-3-327-3456 Report Version : Rev. 02

FAX: 886-3-327-0973






Report No.: FR5N2432AC



EUT take a close-up



EUT take a close-up

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A6 of A6

Report Version

: Rev. 02