


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 7 of 46
EP Report Version : Rev. 01
Issued Date : Nov. 29, 2019








SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 8 of 46
EP Report Version : Rev. 01
Issued Date : Nov. 29, 2019







SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 9 of 46
EP Report Version : Rev. 01
Issued Date : Nov. 29, 2019








SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 10 of 46
EP Report Version : Rev. 01
Issued Date : Nov. 29, 2019









TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 11 of 46
EP Report Version : Rev. 01
Issued Date : Nov. 29, 2019







SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 12 of 46
EP Report Version : Rev. 01
Issued Date : Nov. 29, 2019




Sick Up Cam Wired
FCC ID: 2AEUPBHASC051
IC: 20271-BHASC051
Power input: POE or DC 5V
Patents at: www.nng.com/patents

MAC ID: 3CE1A1613CBC
SKU: 88S1E8-WEN0

S/N: BHSW1850CH010925


Report No.: EP852814-05




SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 13 of 46
EP Report Version : Rev. 01
Issued Date : Nov. 29, 2019









TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 14 of 46
EP Report Version : Rev. 01
Issued Date : Nov. 29, 2019









SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 15 of 46
EP Report Version : Rev. 01
Issued Date : Nov. 29, 2019









SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 16 of 46
EP Report Version : Rev. 01
Issued Date : Nov. 29, 2019









SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 17 of 46
EP Report Version : Rev. 01
Issued Date : Nov. 29, 2019








SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 18 of 46
EP Report Version : Rev. 01
Issued Date : Nov. 29, 2019








SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 19 of 46
EP Report Version : Rev. 01
Issued Date : Nov. 29, 2019









SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 20 of 46
EP Report Version : Rev. 01
Issued Date : Nov. 29, 2019









SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 21 of 46
EP Report Version : Rev. 01
Issued Date : Nov. 29, 2019









SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 22 of 46
EP Report Version : Rev. 01
Issued Date : Nov. 29, 2019









SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 23 of 46
EP Report Version : Rev. 01
Issued Date : Nov. 29, 2019









SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 24 of 46
EP Report Version : Rev. 01
Issued Date : Nov. 29, 2019









SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 25 of 46
EP Report Version : Rev. 01
Issued Date : Nov. 29, 2019









SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 26 of 46
EP Report Version : Rev. 01
Issued Date : Nov. 29, 2019









TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 27 of 46
EP Report Version : Rev. 01
Issued Date : Nov. 29, 2019








SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 28 of 46
EP Report Version : Rev. 01
Issued Date : Nov. 29, 2019









SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 29 of 46
EP Report Version : Rev. 01
Issued Date : Nov. 29, 2019









TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 30 of 46 EP Report Version : Rev. 01

Issued Date : Nov. 29, 2019









TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 31 of 46
EP Report Version : Rev. 01
Issued Date : Nov. 29, 2019








SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 32 of 46
EP Report Version : Rev. 01
Issued Date : Nov. 29, 2019









TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 33 of 46
EP Report Version : Rev. 01
Issued Date : Nov. 29, 2019









SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 34 of 46
EP Report Version : Rev. 01
Issued Date : Nov. 29, 2019







TEL: 886-3-327-3456 FAX: 886-3-327-0973 


 Page No.
 : 35 of 46

 EP Report Version
 : Rev. 01

 Issued Date
 : Nov. 29, 2019







SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : 36 of 46
EP Report Version : Rev. 01
Issued Date : Nov. 29, 2019