



Appendix A. Test Photos

1. Photographs of Conducted Emissions Test Configuration

Mode 1




Report No.: FR532616

: A1 of A4

: Rev. 02

Front view



Rear view

SPORTON INTERNATIONAL INC. Page No. TEL: 886-3-327-3456 Report Version

FAX: 886-3-327-0973



FCC Test Report No.: FR532616



Side view

SPORTON INTERNATIONAL INC. Page No. : A2 of A4
TEL: 886-3-327-3456 Report Version : Rev. 02

FAX: 886-3-327-0973



FCC Test Report


2. Photographs of Radiated Emissions Test Configuration For radiated emissions 9kHz~30MHz

Mode 1



Report No.: FR532616

Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A3 of A4


Report Version : Rev. 02




FCC Test Report

Report No. : FR532616

For radiated emissions 30MHz~1GHz Mode 1



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A4 of A4

Report Version

: Rev. 02