

## Appendix E. Setup Photographs

## <Conducted Emission>



Remote View


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AF5TH1000R Page Number : E1 of E3
Report Issued Date : Oct. 26, 2016
Report Version : Rev. 01

Report No.: FR6O0503B

Report Template No.: BU5-FR15CBT4.0 Version 1.3







Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AF5TH1000R Page Number : E2 of E3
Report Issued Date : Oct. 26, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0 Version 1.3



Report No.: FR6O0503B


## <Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AF5TH1000R Page Number : E3 of E3
Report Issued Date : Oct. 26, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0 Version 1.3