

Appendix C. Setup Photographs

<Conducted Emission>




Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AF5TH1000R Page Number : C1 of C3
Report Issued Date : Oct. 26, 2016
Report Version : Rev. 01

Report No.: FR6O0503A

Report Template No.: BU5-FR15CBT Version 1.1





Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AF5TH1000R Page Number : C2 of C3
Report Issued Date : Oct. 26, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 1.1



Report No.: FR6O0503A


<Radiated Emission>

X Plane

LF







SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AF5TH1000R Page Number : C3 of C3
Report Issued Date : Oct. 26, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 1.1