

Report No.: FR6O0503C


Appendix A. Setup Photographs

<Radiated Emission>

From 9kHz~30MHz



From 30MHz~1GHz



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AF5TH1000R Page Number : A1 of A1 Report Issued Date: Oct. 27, 2016 Report Version : Rev. 01