## 3. Internal Photograph of EUT

Brand Name: BRAGI / Model Name: H1000-0001L

Report No.: EP6O0503-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AF5TH1000L Page Number : 7 of 15 Report Issued Date : Nov. 01, 2016


Report Version : Rev. 01

Report No.: EP6O0503-01




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AF5TH1000L Page Number : 8 of 15
Report Issued Date : Nov. 01, 2016
Report Version : Rev. 01

Report No.: EP6O0503-01




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AF5TH1000L Page Number : 9 of 15
Report Issued Date : Nov. 01, 2016
Report Version : Rev. 01

Report No.: EP6O0503-01




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AF5TH1000L Page Number : 10 of 15
Report Issued Date : Nov. 01, 2016
Report Version : Rev. 01

Report No.: EP6O0503-01




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AF5TH1000L Page Number : 11 of 15
Report Issued Date : Nov. 01, 2016
Report Version : Rev. 01

Report No.: EP6O0503-01




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AF5TH1000L Page Number : 12 of 15
Report Issued Date : Nov. 01, 2016
Report Version : Rev. 01

Report No.: EP6O0503-01




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AF5TH1000L Page Number : 13 of 15
Report Issued Date : Nov. 01, 2016
Report Version : Rev. 01

Report No.: EP6O0503-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AF5TH1000L Page Number : 14 of 15
Report Issued Date : Nov. 01, 2016
Report Version : Rev. 01

Report No.: EP6O0503-01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AF5TH1000L Page Number : 15 of 15
Report Issued Date : Nov. 01, 2016
Report Version : Rev. 01