




Appendix A. Test Photos

1. Photographs of Conducted Emissions Test Configuration



Front View



Side View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A1 of A4

Report Version

: Rev. 01

Report No. : FC843031-01





Report No. : FC843031-01



Under Table View

SPORTON INTERNATIONAL INC. Page No. : A2 of A4
TEL: 886-3-327-3456 Report Version : Rev. 01

FAX: 886-3-327-0973






2. Photographs of Radiated Emissions Test Configuration

For radiated emissions below 1GHz



Front View



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A3 of A4

Report Version

: Rev. 01

Report No.: FC843031-01






Report No.: FC843031-01

For radiated emissions above 1GHz



Front View



Rear View

—THE END———

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A4 of A4

Report Version

: Rev. 01