



153662\_f.JPG: SEAANGEL SA15 AIS FLARE, internal view 1 (housing opened)

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153662E1

 Date of issue:
 16.02.2016
 Order Number:
 15-113662

 page 6 of 15






153662\_g.JPG: SEAANGEL SA15 AIS FLARE, internal view 2 (PCB sandwich removed)

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153662E1

 Date of issue:
 16.02.2016
 Order Number:
 15-113662

 page 7 of 15
 page 7 of 15






153662\_h.JPG: SEAANGEL SA15 AIS FLARE, PCB, top view

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153662E1

 Date of issue:
 16.02.2016
 Order Number:
 15-113662

 page 8 of 15






153662\_I.JPG: SEAANGEL SA15 AIS FLARE, PCB, top view, battery removed

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153662E1

 Date of issue:
 16.02.2016
 Order Number:
 15-113662

 page 9 of 15





153662\_j.JPG: SEAANGEL SA15 AIS FLARE, PCB, bottom view

 Test engineer:
 Thomas KÜHN
 Report Number:
 F153662E1

 Date of issue:
 16.02.2016
 Order Number:
 15-113662

 page 10 of 15