

142199_6.JPG: SEAANGEL SA14, internal view 1 (cover removed)

 Test engineer:
 Thomas KÜHN
 Report Number:
 F142199E1

 Date of issue:
 15 September 2014
 Order Number:
 14-112199
 page 5 of 11






142199_7.JPG: SEAANGEL SA14, internal view 2 (PCB removed)

 Test engineer:
 Thomas KÜHN
 Report Number:
 F142199E1

 Date of issue:
 15 September 2014
 Order Number:
 14-112199
 page 6 of 11






142199_8.JPG: SEAANGEL SA14, PCB, top view

 Test engineer:
 Thomas KÜHN
 Report Number:
 F142199E1

 Date of issue:
 15 September 2014
 Order Number:
 14-112199
 page 7 of 11





142199_9.JPG: SEAANGEL SA14, PCB, bottom view

 Test engineer:
 Thomas KÜHN
 Report Number:
 F142199E1

 Date of issue:
 15 September 2014
 Order Number:
 14-112199
 page 8 of 11