

# Appendix D. Setup Photographs

## <Conducted Emission>



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AFGX-ROBIN Page Number : D1 of D2
Report Issued Date : Jan. 15, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15EWL Version 1.0


Report No.: FR5N2627E




### <Radiated Emission>

#### X Plane

LF



#### HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AFGX-ROBIN Page Number : D2 of D2
Report Issued Date : Jan. 15, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15EWL Version 1.0

Report No.: FR5N2627E