

<Conducted Emission>

Appendix C. Setup Photographs



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AFGX-ROBIN Page Number : C1 of C2
Report Issued Date : Jan. 15, 2016
Report Version : Rev. 01

Report No.: FR5N2627A


Report Template No.: BU5-FR15CBT Version 1.0




<Radiated Emission>

Y Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AFGX-ROBIN Page Number : C2 of C2
Report Issued Date : Jan. 15, 2016
Report Version : Rev. 01

Report No.: FR5N2627A

Report Template No.: BU5-FR15CBT Version 1.0