

# Appendix A. Setup Photographs

# <Conducted Emission>



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AFGX-ROBIN Page Number : A1 of A2
Report Issued Date : Jan. 20, 2016
Report Version : Rev. 01

Report No.: FR5N2627F

Report Template No.: BU5-FR15CNFC Version 1.0




## <Radiated Emission>

### Y Plane

### 9 kHz~30MHz



30MHz~1GHz



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AFGX-ROBIN Page Number : A2 of A2
Report Issued Date : Jan. 20, 2016
Report Version : Rev. 01

Report No.: FR5N2627F

Report Template No.: BU5-FR15CNFC Version 1.0