

Appendix D. Setup Photographs

<Conducted Emission>



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AFGX-ROBIN Page Number : D1 of D2
Report Issued Date : Jan. 15, 2016
Report Version : Rev. 01

Report No.: FR5N2627B

Report Template No.: BU5-FR15CBT4.0 Version 1.1




<Radiated Emission>

Z Plane

LF







SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AFGX-ROBIN Page Number : D2 of D2
Report Issued Date : Jan. 15, 2016
Report Version : Rev. 01

Report No.: FR5N2627B

Report Template No.: BU5-FR15CBT4.0 Version 1.1