

## Appendix D. Setup Photographs

## <Conducted Emission>



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AFGX-ROBIN Page Number : D1 of D2
Report Issued Date : Jan. 15, 2016
Report Version : Rev. 01

Report No.: FR5N2627C


Report Template No.: BU5-FR15CWL Version 1.0




## <Radiated Emission>

## X Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AFGX-ROBIN Page Number : D2 of D2
Report Issued Date : Jan. 15, 2016
Report Version : Rev. 01

Report No.: FR5N2627C

Report Template No.: BU5-FR15CWL Version 1.0