INTERTEK TESTING SERVICE

Report No: HK19030817

Configuration Photographs

Worst-Case Radiated Emissions

(Front View)



INTERTEK TESTING SERVICE

Report No: HK19030817

Configuration Photographs

Worst-Case Radiated Emissions

(Rear View)

