
## Appendix A. Setup Photographs

## <Conducted Emission>

Mode 1





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AFPZ-TGL001 Page Number : A1 of A3
Report Issued Date : Jan. 19, 2018
Report Version : Rev. 01


Report Template No.: BU5-FC15B Version 1.3

Report No. : FC582403-04

Report No. : FC582403-04

Mode 2





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCCID: 2AFPZ-TGL001 Page Number : A2 of A3
Report Issued Date : Jan. 19, 2018
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3

## <Radiated Emission>

## Mode 1

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AFPZ-TGL001 Page Number : A3 of A3
Report Issued Date : Jan. 19, 2018
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3

Report No. : FC582403-04