


Appendix D. Setup Photographs

<Conducted Emission> Mode 1





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AFPZ-TGL001 Page Number : D1 of D2
Report Issued Date : Jan. 19, 2018
Report Version : Rev. 01

Report No.: FR582403-04B


Report Template No.: BU5-FR15CBT4.0 Version 2.0




<Radiated Emission>

Z Plane

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AFPZ-TGL001 Page Number : D2 of D2
Report Issued Date : Jan. 19, 2018
Report Version : Rev. 01

Report No.: FR582403-04B

Report Template No.: BU5-FR15CBT4.0 Version 2.0