## Appendix A. Setup Photographs

## <Conducted Emission>

## Mode 1



Mode 2



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFPZ-TGL001 Page Number : A1 of A2
Report Issued Date : Mar. 15, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.1


Report No.: FC582403

## <Radiated Emission>


Mode 2

X Plane

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFPZ-TGL001 Page Number : A2 of A2
Report Issued Date : Mar. 15, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.1

Report No.: FC582403