

# Appendix C. Setup Photographs

# <Conducted Emission>

#### Mode 1



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFPZ-TGL001 Page Number : C1 of C2
Report Issued Date : Mar. 15, 2016
Report Version : Rev. 01

Report No.: FR582403C


Report Template No.: BU5-FR15CWL Version 1.1




## <Radiated Emission>

### **Z** Plane

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFPZ-TGL001 Page Number : C2 of C2
Report Issued Date : Mar. 15, 2016
Report Version : Rev. 01

Report No.: FR582403C

Report Template No.: BU5-FR15CWL Version 1.1