Appendix A. Setup Photographs

<Conducted Emission>

Mode 4



Mode 5



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-5085G Page Number : A1 of A3
Report Issued Date : Nov. 19, 2015

Report No.: FC582404-01


Report Version : Rev. 01

C Test Report No.: FC582404-01

<Radiated Emission>

Mode 2

LF



HF




SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-5085G Page Number : A2 of A3
Report Issued Date : Nov. 19, 2015
Report Version : Rev. 01


Report No. : FC582404-01

Mode 4

LF



HF



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-5085G Page Number : A3 of A3

Report Issued Date: Nov. 19, 2015

Report Version : Rev. 01