
Appendix A. Setup Photographs

<Conducted Emission>

Mode 2



Mode 3




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-1137 Page Number : A1 of A3
Report Issued Date : Oct. 29, 2015
Report Version : Rev. 01

Report No.: FC581308-01


<Radiated Emission>

Mode 1

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-1137 Page Number : A2 of A3
Report Issued Date : Oct. 29, 2015
Report Version : Rev. 01

Report No. : FC581308-01


Report No. : FC581308-01

Mode 3

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-1137 Page Number : A3 of A3
Report Issued Date : Oct. 29, 2015
Report Version : Rev. 01