

#### Report No.: FR581308-01A

# Appendix B. Setup Photographs

### <Conducted Emission>




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-1137 Page Number : B1 of B2
Report Issued Date : Oct. 29, 2015
Report Version : Rev. 01




## <Radiated Emission>

#### **Z** Plane

LF



HF



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-1137 Page Number : B2 of B2
Report Issued Date : Oct. 29, 2015
Report Version : Rev. 01

Report No.: FR581308-01A