## Appendix C. Test Setup Photographs


## <Radiated Emission>

Y Plane for Part 22H

LF



HF



SPORTON International (ShenZhen) INC.


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-1618 Page Number : C1 of C2
Report Issued Date : Aug. 01, 2017
Report Version : Rev. 01
Report Template No.: BU5-FG22/24 Version 1.2

Report No.: FG762102A




## X Plane for Part 24E

LF



HF



SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-1618 Page Number : C2 of C2
Report Issued Date : Aug. 01, 2017
Report Version : Rev. 01
Report Template No.: BU5-FG22/24 Version 1.2

Report No. : FG762102A