
# Appendix A. Setup Photographs

## <Conducted Emission>

#### Mode 1



Mode 5



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-7558 Page Number : A1 of A3
Report Issued Date : Jan. 23, 2017
Report Version : Rev. 01


Report Template No.: BU5-FC15B Version 1.3

Report No.: FC6N2906


## <Radiated Emission>

## Mode 4

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-7558 Page Number : A2 of A3
Report Issued Date : Jan. 23, 2017
Report Version : Rev. 01


Report Template No.: BU5-FC15B Version 1.3

Report No.: FC6N2906

C Test Report No. : FC6N2906

## Mode 5

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-7558 Page Number : A3 of A3
Report Issued Date : Jan. 23, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3