

Appendix A. Setup Photographs

<Conducted Emission>

Mode 1



Mode 4



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-1157 Page Number : A1 of A3
Report Issued Date : Mar. 21, 2016
Report Version : Rev. 01


Report Template No.: BU5-FC15B Version 1.1

Report No. : FC5D1804-02


<Radiated Emission>

Mode 1

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-1157 Page Number : A2 of A3
Report Issued Date : Mar. 21, 2016
Report Version : Rev. 01


Report Template No.: BU5-FC15B Version 1.1

Report No. : FC5D1804-02


C Test Report No.: FC5D1804-02

Mode 4

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-1157 Page Number : A3 of A3
Report Issued Date : Mar. 21, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.1