


## Report No.: FR762102A

## Appendix B. Setup Photographs

## <Conducted Emission>





SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-1618 Page Number : B1 of B2
Report Issued Date : Aug. 01, 2017
Report Version : Rev. 01


Report Template No.: BU5-FR15CBT Version 2.0




## <Radiated Emission>

X plane

LF



HF



SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-1618 Page Number : B2 of B2
Report Issued Date : Aug. 01, 2017
Report Version : Rev. 01

Report No.: FR762102A

Report Template No.: BU5-FR15CBT Version 2.0