

Report No.: FR582404-01D

Appendix D. Setup Photographs

<Conducted Emission>




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-5085G Page Number : D1 of D2
Report Issued Date : Nov. 19, 2015
Report Version : Rev. 01




Report No.: FR582404-01D

<Radiated Emission>



From 9kHz~30MHz



From 30MHz~1GHz

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-5085G Page Number : D2 of D2
Report Issued Date : Nov. 19, 2015
Report Version : Rev. 01