
Appendix A. Setup Photographs

<Conducted Emission>

Mode 2






Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AFRUHY1-1716 Page Number : A1 of A3
Report Issued Date : Dec. 28, 2017
Report Version : Rev. 01


Report Template No.: BU5-FC15B Version 1.3

Report No.: FC7N1621



Mode 6





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AFRUHY1-1716 Page Number : A2 of A3
Report Issued Date : Dec. 28, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3


<Radiated Emission>

Mode 6

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AFRUHY1-1716 Page Number : A3 of A3
Report Issued Date : Dec. 28, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3

Report No.: FC7N1621