3. Internal Photograph of EUT


Brand Name: HYUNDAI; Model Name: HY1-1157

Report No.: EP5D1804-02




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-1157 Page Number : 13 of 30
Report Issued Date : Mar. 21, 2016
Report Version : Rev. 01

Brand Name: HYUNDAI; Model Name: HY1-1157




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-1157 Page Number : 14 of 30
Report Issued Date : Mar. 21, 2016
Report Version : Rev. 01

Report No.: EP5D1804-02



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-1157 Page Number : 15 of 30
Report Issued Date : Mar. 21, 2016
Report Version : Rev. 01

Report No.: EP5D1804-02




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-1157 Page Number : 16 of 30
Report Issued Date : Mar. 21, 2016

Report Version : Rev. 01




Report No.: EP5D1804-02




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-1157 Page Number : 17 of 30
Report Issued Date : Mar. 21, 2016
Report Version : Rev. 01

Report No.: EP5D1804-02




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-1157

Report No.: EP5D1804-02




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-1157 Page Number : 19 of 30
Report Issued Date : Mar. 21, 2016
Report Version : Rev. 01

Report No.: EP5D1804-02



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-1157 Page Number : 20 of 30
Report Issued Date : Mar. 21, 2016
Report Version : Rev. 01




SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-1157 Page Number : 21 of 30
Report Issued Date : Mar. 21, 2016
Report Version : Rev. 01




Report No.: EP5D1804-02



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-1157 Page Number : 22 of 30 Report Issued Date : Mar. 21, 2016 Report Version : Rev. 01




Report No.: EP5D1804-02




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-1157 Page Number : 23 of 30 Report Issued Date : Mar. 21, 2016 Report Version : Rev. 01

Report No.: EP5D1804-02




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-1157 Page Number : 24 of 30
Report Issued Date : Mar. 21, 2016
Report Version : Rev. 01

Report No.: EP5D1804-02




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-1157 Page Number : 25 of 30
Report Issued Date : Mar. 21, 2016
Report Version : Rev. 01

Brand Name: HYUNDAI; Model Name: HY1-1157




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-1157 Page Number : 26 of 30
Report Issued Date : Mar. 21, 2016
Report Version : Rev. 01

Report No.: EP5D1804-02




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-1157 Page Number : 27 of 30
Report Issued Date : Mar. 21, 2016
Report Version : Rev. 01

Report No.: EP5D1804-02




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-1157 Page Number : 28 of 30
Report Issued Date : Mar. 21, 2016
Report Version : Rev. 01



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-1157 Page Number : 29 of 30 Report Issued Date : Mar. 21, 2016

: Rev. 01 Report Version

Report No.: EP5D1804-02



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-1157 Page Number : 30 of 30
Report Issued Date : Mar. 21, 2016
Report Version : Rev. 01