Appendix C. Setup Photographs


<Radiated Emission>

Z Plane for Part 22H

LF



HF



Sporton International (Shenzhen) Inc.


TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AFRUHY1-1716 Page Number : C1 of C2
Report Issued Date : Dec. 28, 2017
Report Version : Rev. 01

Report No. : FG7N1621A


Report Template No.: BU5-FG22/24 Version 1.2

X Plane for Part 24E

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AFRUHY1-1716 Page Number : C2 of C2
Report Issued Date : Dec. 28, 2017
Report Version : Rev. 01
Report Template No.: BU5-FG22/24 Version 1.2

Report No.: FG7N1621A