
# Appendix B. Setup Photographs

## <Conducted Emission>

#### Mode 1




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-1157 Page Number : B1 of B2
Report Issued Date : Mar. 21, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 1.0

Report No.: FR5D1804-02A


# <Radiated Emission>

## **Z** Plane

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-1157 Page Number : B2 of B2
Report Issued Date : Mar. 21, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 1.0

Report No.: FR5D1804-02A