


Report No.: FR582404-01C

Appendix C. Setup Photographs

<Conducted Emission>



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-5085G Page Number : C1 of C2
Report Issued Date : Nov. 19, 2015
Report Version : Rev. 01




Report No.: FR582404-01C


<Radiated Emission>

Y Plane

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-5085G Page Number : C2 of C2
Report Issued Date : Nov. 19, 2015
Report Version : Rev. 01