


<Conducted Emission>

Appendix C. Setup Photographs



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFRUHY26275AZ Page Number : C1 of C3
Report Issued Date : Nov. 10, 2015
Report Version : Rev. 01


Report No.: FR531002-01C




<Radiated Emission>

X plane

LF



HF



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFRUHY26275AZ Page Number : C2 of C3
Report Issued Date : Nov. 10, 2015
Report Version : Rev. 01


Report No.: FR531002-01C






Y plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFRUHY26275AZ Page Number : C3 of C3
Report Issued Date : Nov. 10, 2015
Report Version : Rev. 01

Report No.: FR531002-01C