
## 3. Internal Photograph of EUT

Brand Name: HYUNDAI; Model Name: HY1-1716

Report No.: EP7N1621




## Note:

Specification of Antenna	
WWAN Antenna Top	Support WCDMA Band V
WWAN Antenna Bottom	Support GSM 850/1900, WCDMA Band II, LTE Band 4

Sporton International (Shenzhen) Inc.


TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AFRUHY1-1716 Page Number : 12 of 39
Report Issued Date : Dec. 28, 2017
Report Version : Rev. 01

Report No.: EP7N1621




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AFRUHY1-1716 Page Number : 13 of 39
Report Issued Date : Dec. 28, 2017
Report Version : Rev. 01

Report No.: EP7N1621




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AFRUHY1-1716 Page Number : 14 of 39
Report Issued Date : Dec. 28, 2017

Report No.: EP7N1621



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AFRUHY1-1716 Page Number : 15 of 39
Report Issued Date : Dec. 28, 2017


Report No.: EP7N1621



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AFRUHY1-1716 Page Number : 16 of 39
Report Issued Date : Dec. 28, 2017




Report No.: EP7N1621



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AFRUHY1-1716 Page Number : 17 of 39 Report Issued Date : Dec. 28, 2017




Report No.: EP7N1621




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AFRUHY1-1716 Page Number : 18 of 39
Report Issued Date : Dec. 28, 2017

Report No.: EP7N1621



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AFRUHY1-1716 Page Number : 19 of 39
Report Issued Date : Dec. 28, 2017
Report Version : Rev. 01

Report No.: EP7N1621



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AFRUHY1-1716 Page Number : 20 of 39
Report Issued Date : Dec. 28, 2017


Report No.: EP7N1621



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AFRUHY1-1716 Page Number : 21 of 39 Report Issued Date : Dec. 28, 2017

Report No.: EP7N1621




Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AFRUHY1-1716 Page Number : 22 of 39
Report Issued Date : Dec. 28, 2017
Report Version : Rev. 01




Report No.: EP7N1621



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AFRUHY1-1716 Page Number : 23 of 39
Report Issued Date : Dec. 28, 2017


Report No.: EP7N1621



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AFRUHY1-1716 Page Number : 24 of 39
Report Issued Date : Dec. 28, 2017


Report No.: EP7N1621



Sporton International (Shenzhen) Inc.


TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AFRUHY1-1716 Page Number : 25 of 39
Report Issued Date : Dec. 28, 2017
Report Version : Rev. 01

Report No.: EP7N1621




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AFRUHY1-1716 Page Number : 26 of 39
Report Issued Date : Dec. 28, 2017

Report No.: EP7N1621



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AFRUHY1-1716 Page Number : 27 of 39
Report Issued Date : Dec. 28, 2017
Report Version : Rev. 01


Report No.: EP7N1621



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AFRUHY1-1716 Page Number : 28 of 39
Report Issued Date : Dec. 28, 2017
Report Version : Rev. 01




Report No.: EP7N1621



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AFRUHY1-1716 Page Number : 29 of 39
Report Issued Date : Dec. 28, 2017

Report No.: EP7N1621




Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AFRUHY1-1716 Page Number : 30 of 39
Report Issued Date : Dec. 28, 2017




Report No.: EP7N1621



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AFRUHY1-1716 Page Number : 31 of 39


Report Issued Date : Dec. 28, 2017

Report No.: EP7N1621




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AFRUHY1-1716 Page Number : 32 of 39 Report Issued Date : Dec. 28, 2017

Report No.: EP7N1621



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AFRUHY1-1716 Page Number : 33 of 39 Report Issued Date : Dec. 28, 2017


Report No.: EP7N1621



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AFRUHY1-1716 Page Number : 34 of 39


Report Issued Date : Dec. 28, 2017

Report No.: EP7N1621



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AFRUHY1-1716 Page Number : 35 of 39 Report Issued Date : Dec. 28, 2017


Report No.: EP7N1621



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AFRUHY1-1716 Page Number : 36 of 39
Report Issued Date : Dec. 28, 2017


Report No.: EP7N1621




TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AFRUHY1-1716 Page Number : 37 of 39
Report Issued Date : Dec. 28, 2017




Report No.: EP7N1621



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AFRUHY1-1716 Page Number : 38 of 39
Report Issued Date : Dec. 28, 2017



Report No.: EP7N1621



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AFRUHY1-1716 Page Number : 39 of 39
Report Issued Date : Dec. 28, 2017