

Appendix A. Setup Photographs

<Conducted Emission>

Mode 1



Mode 5



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-7372 Page Number : A1 of A3
Report Issued Date : Oct. 27, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3

Report No.: FC6O0902


<Radiated Emission>

Mode 4

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-7372 Page Number : A2 of A3
Report Issued Date : Oct. 27, 2016
Report Version : Rev. 01


Report Template No.: BU5-FC15B Version 1.3

Report No.: FC6O0902


Test Report No. : FC6O0902

Mode 5

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-7372 Page Number : A3 of A3
Report Issued Date : Oct. 27, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3