


## Appendix D. Setup Photographs

## <Conducted Emission>





TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-1618 Page Number : D1 of D2
Report Issued Date : Aug. 01, 2017

Report No.: FR762102C

Report Version : Rev. 01

Report Template No.: BU5-FR15CWLAN Version 2.0




## Test Report No. : FR762102C


## <Radiated Emission>

X Plane

LF



HF



SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-1618 Page Number : D2 of D2
Report Issued Date : Aug. 01, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CWLAN Version 2.0