


Report No.: FR6N2906C

<Conducted Emission>

Appendix D. Setup Photographs

Mode 1



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-7558 Page Number : D1 of D2 Report Issued Date: Jan. 23, 2017 Report Version : Rev. 01


Report Template No.: BU5-FR15CWL Version 1.3




Report No.: FR6N2906C

<Radiated Emission>

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY1-7558 Page Number : D2 of D2
Report Issued Date : Jan. 23, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL Version 1.3