
# Appendix A. Setup Photographs

### <Conducted Emission>

### Mode 7





Sporton International (Shenzhen) Inc.


TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: Y2AFRUHY1-1713 Page Number : A1 of A3
Report Issued Date : Dec. 04, 2017
Report Version : Rev. 01


Report Template No.: BU5-FC15B Version 1.3

Report No. : FC7O1303



Mode 4





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: Y2AFRUHY1-1713 Page Number : A2 of A3 Report Issued Date: Dec. 04, 2017 Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3

Report No.: FC7O1303


## <Radiated Emission>

### Mode 4

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: Y2AFRUHY1-1713 Page Number : A3 of A3
Report Issued Date : Dec. 04, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3

Report No.: FC7O1303