1. External Photograph of EUT

Brand Name: HYUNDAI / Model Name: HY2-6275AZ

Report No.: EP531002-01



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY26275AZ Page Number : 1 of 28

Report Issued Date : Nov. 10, 2015 Report Version : Rev. 01




SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY26275AZ Page Number : 2 of 28

Report Issued Date : Nov. 10, 2015 Report Version : Rev. 01

Report No.: EP531002-01



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY26275AZ Page Number

: 3 of 28


Report Issued Date : Nov. 10, 2015

Report Version

: Rev. 01








TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY26275AZ Page Number : 4 of 28 Report Issued Date : Nov. 10, 2015

Report Version : Rev. 01





Report No.: EP531002-01



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY26275AZ Page Number : 5 of 28 Report Issued Date : Nov. 10, 2015

Report Version : Rev. 01





SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY26275AZ Page Number : 6 of 28

Report Issued Date : Nov. 10, 2015

Report Version : Rev. 01

2. Photograph of Accessory

Brand Name: HYUNDAI / Model Name: HY2-6275AZ

Report No.: EP531002-01

Specification of Accessory		
AC Adapter	Brand Name	BLU
	Model Name	US-KT-1000
Battery	Brand Name	HYUNDAI
	Model Name	TBW5726
Earphone	Signal Line Type	1.2m non-shielded cable without ferrite core
USB Cable	Signal Line Type	1.0m non-shielded cable without ferrite core

Remark: For accessories equipped with this EUT, please refer to the following photos.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY26275AZ Page Number : 7 of 28
Report Issued Date : Nov. 10, 2015
Report Version : Rev. 01



Report No.: EP531002-01



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY26275AZ

: 8 of 28 Page Number

Report Issued Date : Nov. 10, 2015 Report Version : Rev. 01

Report No.: EP531002-01



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY26275AZ Page Number : 9 of 28
Report Issued Date : Nov. 10, 2015

Report Version : Rev. 01




Report No.: EP531002-01



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY26275AZ Page Number : 10 of 28 Report Issued Date : Nov. 10, 2015 : Rev. 01 Report Version



Report No.: EP531002-01



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFRUHY26275AZ Page Number : 11 of 28 Report Issued Date : Nov. 10, 2015 Report Version : Rev. 01