# **BLOCKS**

# Important Information

## Important Safety Instructions

- (1) Read these instructions.
- (2) Keep these instructions
- (3) Heed all warnings
- (4) Follow all instructions.
- (5) Do not use this apparatus near water
- (6) Clean only with dry cloth.
- (7) Do not block any ventilation openings. Install in accordance with the manufacturer's instructions.
- (8) Do not install near any heat sources such as radiators, heat registers, stoves, or other apparatus (including amplifiers) that produce heat.
- (g) Only use attachments/accessories specified by the manufacturer.
- (10) Unplug this apparatus during lightning storms or when unused for long periods of time.
- (1) Refer all servicing to qualified service personnel. Servicing is required when the apparatus has been damaged in any way, such as power-supply cord or plug is damaged, liquid has been spilled or objects have fallen into the apparatus, the apparatus has been exposed to rain or moisture, does not operate normally, or has been dropped.

# FCC Statement

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:

- (1) this device may not cause harmful interference, and
- (2) this device must accept any interference received, including interference that may cause undesired operation

No changes shall be made to the equipment without the manufacturer's permission as this may void the user's authority to operate the equipment.

Note: This equipment has been tested and found to comply with the limits for a Class B digital device, pursant to part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation.

If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.

This device complies with the FCC safety requirements for RF exposure in accordance with FCC rule part §2.1093

#### Industry Canada Statement

"This device complies with Industry Canada's licence-exempt RSSs. Operation is subject to the following two conditions:

- (1) This device may not cause interference; and
- (2) This device must accept any interference, including interference that may cause undesired operation of the device"

This device complies with the safety requirement for RF exposure in accordance with RSS-102, issue 5 for portable conditions.

# Pour les usagers r sidant au Canada

Le pr sent appareil est conforme aux CNR du ISDE applicables aux appareils radio exempts de licence.

L'exploitation est autoris e aux deux conditions suivantes :

- (1) l'appareil ne doit pas produire de brouillage, et
- (2) l'utilisateur de l'appareil doit accepter tout brouillage radio lectrique subi, m me si le brouillage est susceptible d'en compromettre le fonctionnement.

Cet appareil est conforme aux limites d'exposition humaine aux radiofr quences pour les ordinateurs portables, conform ment au CNR 102, 5 me dition

# Europe (R&TTE Directive)

Declaration of Conformity to R&TTE Directive, 1999/5/EC:

Hereby, ROLI Ltd, declares that this Seaboard Block is in compliance with the essential requirements and other relevant provisions of Directive 1999/5/EC.

ROLI Ltd, vakuuttaa† ten ett Seaboard Block tyyppinen laite on direktiivin 1999/5/EY oleellisten vaatimusten ja sit koskevien direktiivin muiden ehtojen mukainen.





Hierbij verklaart ROLI Ltd, dat het toestel Seaboard Block in overeenstemming is met de essenti le eisen en de andere relevante bepalingen van richtlijn 1999/5/EG

Par la pr sente, ROLI Ltd, d' clare que ce Seaboard

Block est conforme aux exigences essentielles et aux autres
dispositions de la directive 1999/5/CE qui lui sont applicables

H rmed infygar ROLI Ltd, att denna Seaboard
Block st r I verensst mmelse med de v sentliga egenskapskrav och
vriga relevanta best mmelser som framg r av direktiv 1999/5/EG.

Undertegnede ROLI Ltd, erklærer herved, at følgende udstyr Seaboard Block overholder de væsentlige krav og øvrige relevante krav i direktiv 1999/5/EF

Hiermit erkl rt ROLI Ltd., dass sich dieser

Seaboard Block in bereinstimmung mit den grundlegenden Anforderungen und den anderen relevanten Vorschriften der Richtlinie 1909/5/EG hafindet

### ΜΕ 6Ν ΠΑΡΟΥΣΑ ROLI Ltd, ΔΗΛΩΝΕΙ ΟΤΙ Seaboard Βίος ΚΣΥΜΜΟΡΦΩΝΕΤΑΙ ΠΡΟΣ ΤΙΣ ΟΥΣΙΩΔΕΙΣ ΑΠΑΙΘΣΕΙΣ ΚΑΙ ΤΙΣ ΛΟΠΕΣ ΣΧΕΤΙΚΈΣ ΔΙΑΤΑΞΕΙΣ ΤΗΣ ΟΔΗΓΙΑΣ 1999/5/ΕΚ

Con la presente ROLI Ltd, dichiara che questo Seaboard Block conforme ai requisiti essenziali ed alle altre disposizioni pertinenti stabilite dalla direttiva 1999/5/CE.

Por medio de la presente ROLI Ltd, declara que el Seaboard Block cumple con los requisitos esenciales y cualesquiera otras disposiciones aplicables o exigibles de la Directiva 1999/5/CE

ROLI Ltd, declara que este Seaboard Block est conforme com os requisitos essenciais e outras disposiç es

A signed copy of the full Declaration of Conformity is available from https://support.roli.com.

### Mexican Statement

da Directiva 1999/5/CE

La operaci n de este equipo est sujeta a las siguientes dos condiciones

- Es posible que este equipo o dispositivo no cause interferencia periudicial.
- (2) Este equipo o dispositivo debe aceptar cualquier interferencia. Incluyendo la que pueda causar su operaci n no deseada.

#### Cautions

This product does not contain any user serviceable parts, including the battery, and should not be opened. Danger of explosion if battery is incorrectly replaced. Replace only with the same or equivalent type.

ROLI Ltd., 2 Glebe Road, London, England, E8 4BD, www.roli.com

