Appendix A. Setup Photographs

<Conducted Emission>

Mode 2



Mode 3



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFWFS6 Page Number : A1 of A3
Report Issued Date : Feb. 17, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.1


Report No.: FC610605

CC Test Report No. : FC610605

Mode 2

<Radiated Emission>

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFWFS6 Page Number : A2 of A3
Report Issued Date : Feb. 17, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.1

C Test Report No. : FC610605

Mode 3

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFWFS6 Page Number : A3 of A3
Report Issued Date : Feb. 17, 2016
Report Version : Rev. 01
Report Template No.: BU5-FC15B Version 1.1