

Appendix B. Setup Photographs

<Conducted Emission>

Mode 1



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFWFS6 Page Number : B1 of B2
Report Issued Date : Feb. 17, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0 Version 1.1


Report No.: FR610605B




<Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFWFS6 Page Number : B2 of B2
Report Issued Date : Feb. 17, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT4.0 Version 1.1

Report No.: FR610605B