

Appendix A. Setup Photographs

<Conducted Emission>

Mode 1



Mode 2



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFWMLEX727 Page Number : A1 of A2
Report Issued Date : Oct. 17, 2016
Report Version : Rev. 01

Report No.: FC6O1404

Report Template No.: BU5-FD15B Version 1.3


<Radiated Emission>




Report No.: FC6O1404

Mode 1

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: 2AFWMLEX727

Page Number : A2 of A2 Report Issued Date: Oct. 17, 2016 Report Version : Rev. 01

Report Template No.: BU5-FD15B Version 1.3