
Appendix C. Setup Photographs


<Radiated Emission>

Y Plane for LTE Band 2 / 12 / 17 / 26

LF



HF




SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFWMLE1PRO Page Number : C1 of C4
Report Issued Date : Sep. 29, 2015


Report No.: FG582501B

X Plane for LTE Band 4

LF



HF




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFWMLE1PRO Page Number : C2 of C4
Report Issued Date : Sep. 29, 2015


Report No. : FG582501B

Z Plane for LTE Band 5

LF



HF




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFWMLE1PRO Page Number : C3 of C4
Report Issued Date : Sep. 29, 2015


Report No. : FG582501B

X Plane for LTE Band 25

LF



HF



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AFWMLE1PRO Page Number : C4 of C4
Report Issued Date : Sep. 29, 2015

Report No. : FG582501B